

# DESCO INDUSTRIES INCORPORATED

3651 Walnut Ave. Chino, CA 91710 Phone (909) 627-8178 Fax (909) 627-7449

---

## CAL BOX CALIBRATION

1. Remove back cover.
2. Measure each range and adjust the appropriate trimpot to yield the correct resistance within +/- 2%.
3. Close the unit and return to service.

